

Oil Field Environmental Incident Summary

Incident: 20151006081702 **Date/Time of Notice:** 10/06/2015 08:17

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: EN-HORST-154-93- 0310H-1

Field Name: ROBINSON LAKE

Well File #: 16981

Date Incident: 10/4/2015 **Time Incident:** 08:30

Facility ID Number:

County: MOUNTRAIL

Twp: 154

Rng: 93

Sec: 3

Qtr:

Location Description:

Submitted By: Alex Beach

Received By:

Contact Person: Jason Henry
3015 16th Street South, Suite 20
Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.6 Mile

Distance Nearest Water Well: 0.6 Mile

Type of Incident: Truck Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	41	Barrels				

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

There is no immediate risk to report at this time.

Areal Extent:

150' by 100'

Potential Environmental Impacts:

There are no potential environmental impacts to report at this time. All impacted material is onsite.

Action Taken or Planned:

Upon discovery of the release, Hess was notified. Hess dispatched a vacuum truck to recover the free liquids. A North Dakota One-Call was initiated. The remaining remediation work will start when the One-Call clears.

Wastes Disposal Location: All of the recovered waste will be disposed of at an approved waste disposal facility.

Agencies Involved:**Updates**

Date: 10/6/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Tintes Schiwal, Emily

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spill remained on well site. NDIC retains oversight.